MITIGATION SITE

4-3-92

1. IRRIGATION DITCH LOOKING WEST FROM THE MAIN ENTERANCE

2. MITIGATION SITE LOOKING SOUTH WEST FROM THE MAIN ENTERANCE.

3. BARB WIRE FENCING.

MITIGATION SITE

12-12-91

1. IRRIGATION DITCH NORTH EAST CORNER LOOKING WEST

2. IRRIGATION DITCH NORTH EAST CORNER LOOKING SOUTH

3. WELL SITE LOOKING NORTH

4. IRRIGATION DITCH WITH FLOW GATES LOOKING SOUTH WEST

MITIGATION SITE
10-3-91

1. SOUTH WEST CORNER LOOKING NORTH EAST

2. SOUTH WEST CORNER LOOKING UP TEST BASIN

3. SAINT JOHNS TAIL WATER PIPE LOOKING NORTH

4. BRIDGE OVER BUCKEYE IRRIGATION DITCH LOOKING SOUTH WEST

5. MITIGATION SITE MAIN ENTRANCE GATE LOOKING EAST

6. NORTH WEST CORNER LOOKING EAST TOWARD MAIN ENTRANCE GATE

7. NORTH WEST CORNER LOOKING SOUTH WEST AREA TO BE SEEDED

8. WESTERLY BRIDGE OVER IRRIGATION DITCH LOOKING WEST

9. WELL SITE LOOKING NORTH EAST.

10. WELL SITE LOOKING WEST

10-3-91

11. LOOKING NORTH WEST FROM THE IRRIGATION GATES

12. IRRIGATION GATES AND DITCH LOOKING SOUTH

13. IRRIGATION DITCH EAST SIDE LOOKING WEST

14 EASTERLY IRRIGATION DITCH SOUTH END LOOKING NORTH.

MITIGATION SITE

10-6-91

1. LOOKING N.E. AT WELL & MAINTENANCE Rd.

2. STANDING AT IRRIGATION STRUCTURES LOOKING S.W. AT GRADED FIELD

3. IRRIGATION DITCH REPAIRS LOOKING WEST

NO TRESPASSING

ING
SSING
AREA

MITIGATION SITE


AVONDALE
27
AVONDALE
LIMITS
CITY
OS
34

10-03-91

SOUTH WEST CORNER LOOKING NORTH EAST

1

10-03-91

SOUTH WEST CORNER LOOKING UP TEST BASIN

2

10-03-91

SAINT JOHNS TAIL WATER PIPE LOOKING NORTH

3

10-03-91

BRIDGE OVER BUCKEYE IRRIGATION DITCH

LOOKING SOUTH WEST

4

10-03-91

MITIGATION SITE MAIN ENTRANCE GATE

LOOKING EAST

5

10-03-91

NORTH WEST CORNER LOOKING EAST TOWARD

MAIN ENTRANCE GATE

6

10-03-91

NORTH WEST CORNER LOOKING SOUTH WEST

AREA TO BE SEEDED

7

10-03-91

WESTERLY BRIDGE OVER IRRIGATION DITCH

LOOKING WEST

8

10-03-91

WELL SITE LOOKING NORTH EAST

9

10-03-91

WELL SITE LOOKING WEST

10

10-03-91

LOOKING NORTH WEST FROM IRRIGATION GATES

11

10-03-91

IRRIGATION GATES AND DITCH LOOKING SOUTH

12

10-03-91

IRRIGATION DITCH EAST SIDE LOOKING WEST

13

10-03-91

EASTERLY IRRIGATION DITCH SOUTH END

LOOKING NORTH

14

LOOKING N.E. AT WELL & MAINTENANCE ROAD

10-06-91

STANDING AT IRRIGATION STRUCTURES LOOKING S.W. AT GRADED FIELD

10-06-91

IRRIGATION DITCH REPAIRS LOOKING WEST

10-06-91

IRRIGATION DITCH NORTHEAST CORNER

LOOKNG WEST

12-12-91

IRRIGATION DITCH NORTHEAST CORNER

LOOKING SOUTH

12-12-91

WELL SITE LOOKING NORTH

12-12-91

IRRIGATION DITCH WITH FLOW GATES

LOOKING SOUTHWEST

12-12-91