FCD Photos 1990-1992

Waterman Wash Flowing Water 1990

Happy Valley Road North of CAP Ponding & Plugging 1990

Cave Creek Road Flooding 1990

Cave Creek Dam Water Behind Dam 1990

Pinnacle Peak Road & 19th Avenue Ponding 1990

ACDC Flooding & Erosion 1990

Indian Bend Wash Flooding 1990

Gila River at Gila Bend Storm Event 1990

Laveen at La Mirada Drive Breech in Irrigation Channel 1990

43rd Ave & Campion Drain & Baseline & Southern Flooding 1990

35th Ave, 43rd Ave, 48th Ave/Indian School /Buckeye Flooding 1992

Crossroads Park Flooding & Erosion 1992

Waterman Wash Flowing Water 1990

Happy Valley Road North of CAP Ponding & Plugging 1990

Property of
Flood Control District of MC Library
Please Return to
2801 W. Durango
Phoenix, AZ 85009

Cave Creek Road Flooding 1990

Cave Creek Dam Water Behind Dam 1990

Pinnacle Peak Road & 19th Avenue Ponding 1990

ACDC Flooding & Erosion 1990

Indian Bend Wash Flooding 1990

Gila River at Gila Bend Storm Event 1990

Laveen at La Mirada Drive Breech in Irrigation Channel 1990

43rd Ave & Campion Drain & Baseline & Southern Flooding 1990

35th Ave, 43rd Ave, 48th Ave/Indian School /Buckeye Flooding 1992

Crossroads Park Flooding & Erosion 1992

Waterman Wash Flowing Water 1990

Happy Valley Road North of CAP Ponding & Plugging 1990

~~55~~ 1

WATERMAN WASH looking W. on Eagle Mtn Rd 3' vertical Bank cut; water w/ 1' Deep, 4 FPS 7/24/90 11:00 A.M.

~~57~~ 3

WATERMAN WASH looking W. on Eagle Mtn. Rd. 3' vertical Bank cut; water w/ 1' Deep, 4 FPS 7/24/90 11:00 A.M.

~~56~~ 2

7/24/90
Waterman wash looking W. on Eagle Mtn Rd. 3' vertical Bank cut; water w/ 1' Deep, 4 FPS

CAP ponding at 1st overchute North of Happy Valley Rd

8-15-90 10:30 AM

RWC

CAP overchute, 1st one North of Happy Valley Rd (showing plugging)

8-15-90 10:30 AM

RWC

CAP ponding at 1st overchute North of Happy Valley Rd

8-15-90 10:30 AM

RWC

CAP culvert, 1st one North of Happy Valley Rd (showing plugging) 7

8-15-90 10:30 A.M.

RWC

CAP ponding north of Happy Valley Road 8

8-15-90 10:00 A.M.

RWC

CAP ponding North of Happy Valley Rd 9

8-15-90 10:00 A.M.

RWC

CAP ponding nr Powerlines South of Happy Valley Rd

10

8-15-90 10:00 AM
RWC

Happy Valley Rd ab CAP looking South

11

8-15-90 9:30 AM
RWC

Happy Valley Rd, East of I-17

12

8-15-90 9:00 A.M.
RWC

Happy Valley Rd, East of I-17 13
8-15-90 9:00 A.M.
RWC

8/15/90 11:00 AM 14
Cave Creek below 7th St.

Cave Creek at Beardsley Rd. 15
8-15-90 ; 11:00 AM

Cave Creek Road Flooding 1990

Cave Creek Dam Water Behind Dam 1990

Pinnacle Peak Road & 19th Avenue Ponding 1990

Water behind Cave Creek Dam
1990

28

19th Ave, North of Pinnacle Pk Rd, looking South at flow from dike of Track.

8-15-90 9:30 A.M.

RWC

29

19th Ave, looking South towards Pinnacle Peak Rd

8-15-90 9:30 A.M.

RWC

30

Ponding at track on NE corner of 19th Ave & Pinnacle Pk Rd. 31

8-15-90 9:30 AM.

RWC

59th Ave @ Greenway Rd 32

looking North

8-15-90 1:30 PM

RWC

ACDC Flooding & Erosion 1990

Indian Bend Wash Flooding 1990

FLASH
FLOOD
AREA

33

Erosion, south bank
ACDC, Sept. 4, 1990

34

Upstream of ACDC at
67th Ave.
sept. 4, 1990

35 ACDC Reach 1 7-16-91
at 67th Ave

36

67th Ave. Bridge across ACDC
8/15/90

37

IBW - Indian Bend Rd.
7/24/90

38

IBW - Indian Bend Basin
7/24/90

39

IBW - McKellips Rd.

7/24/90

40

IBW - Indian Bend Basin

looking downstream

7/24/90

41

IBW - McCormick Ranch Rd.

7/24/90

42

Indian Bend Wash
chaparral Rd. looking upstream
7/24/90

43

Indian Bend Wash
S. of chaparral Rd.
7/24/90

Gila River at Gila Bend Storm Event 1990

Laveen at La Mirada Drive Breech in Irrigation Channel 1990

C-LINE #52584
35MM PRINTS

47

Aug. 16, 1990 Storm Event

SR 85 & Gila River

45

Aug. 16, 1990 Storm Event

Ponding caused by overtopping of canal (Gila Bend Canal).

Vicinity of Gila River & SR 85

Gila River @ Gila Bend

50

Aug. 16, 1990 Storm Event

Gila River near SR 85 in Gila Bend

49

Aug. 16, 1990 Event

SR 85 & Gila River in Gila Bend

C-LINE #52584
35MM PRINTS

46

Aug. 16, 1990 Storm Event

SR 85 & Gila River

48

Aug. 16, 1990 Event

Gila River in vicinity of

SR 85 in Gila Bend

44

Aug. 16, 1990 Event

SR 85 and Gila River

Debris blocking culvert

51

August 16, 1990 Event

Gila River in Gila Bend

Laveen

52

Looking east along Dobbins
at 43rd Ave.
8/14/90

Loveen

53

Breach in irrigation channel at
Piedmont Rd. in Loveen,
(Looking to the east)
8/14/90

54

Breach in irrigation channel
at La Mirada Dr., Loveen
(Looking to the east)
8/14/90

55

Attempted channel at administrative building, Laveen

8/14/90

56

Attempted channel at administrative building in Laveen.

8/16/90

LAVEEN
SLIDE
1992

"3rd Ave. + Southern"

LAVEEN

23

43rd Ave & Campion Drain & Baseline & Southern Flooding 1990

Baseline & 35th Ave.
(by Alvord Park)
8/14/90

Start of Champion Drain
at 43rd Ave & Alta Vista Rd.
8/14/90

Champion Drain area,
1/4 mi S. of Southern
Ave on 43rd Ave
8/14/90

60 Champion Drain Area
~ 1/4 mi. s. of Southern Ave.
on 43rd Ave.
8/14/90

61

6645 43rd Ave - between Baseline and Southern

8/14/90 T.W.H.

North side of Baseline at 43rd Ave

62

8/14/90 T.W.H.

43rd Ave and W. Alta Vista

63

8/14 T.W.H.

3414 43rd Ave
(south of Lower Buckeye)

64

8/14/90 T.W.H.

65 Storm sewer overflow at
43rd Ave & Lower Buckeye
8/14/90

35th Ave, 43rd Ave, 48th Ave/Indian School /Buckeye Flooding 1992

69

East Bound on-ramp onto
Indian School from 35th Ave.
7/24/92

68

Indian School at 35th Ave
looking west 7/24/92

C-LINE #52584
35MM PRINTS

67

Indian School overpass at
35th Ave, looking W 7/24/92

66

Indian School Rd. at 35th
Ave., looking West 7/24/92

7/24/92 71

6625 S. 43rd Ave
Breaching Berm to alleviate Flooding

7/24/92 72

6625 S. 43rd Ave
looking N. on 43rd Ave

74

Lower Buckeye & 48th Ave 7/24/92
Canal overflow, looking South
(Standing South of L-3)

7/24/92 11:00 am 73

48th Ave Drain at
48th St. looking D.S (High Water)

7/24/92 70

6600 S. 43rd Ave
looking N. on 43rd at Alta Vista

Crossroads Park Flooding & Erosion 1992

75

CROSSROADS PARK. JULY 28,92
STORM WATER HAS UNDERMINED GROUTED
RIP RAP AT INLET STRUCTURE #1.
GULLY IS OVER 4' WIDE AND 5' DEEP

76

CROSSROADS PARK. T·24·92 12 NOON
DEEP EROSION OF LAKE SLOPES AT
SEVERAL PLACES DUE TO THE STORM

77

CROSSROADS PARK. T·24·92 12 NOON
SRP DITCH FLOWING FULL

78

CROSSROADS PARK. T·24·92 NOON
FLOODWATERS FLOWING OVER INLET
ST #1 INTO THE LAKE

C-LINE #52584
35MM PRINTS

80

CROSSROADS PARK. 7.24.92, 12 NOON
WATER FLOWING OVER INLET ST #1
AND IN TO THE LAKE

79

CROSSROADS PARK - JULY 28, 92
STORM WATER UNDERMINED GROUTED
RIP RAP AT INLET STRUCTURE #1.
OPENING 4' WIDE X OVER 5' DEEP
AT PLACES.

82

CROSSROADS PARK JULY 28, 92.
BASIN STILL HAS OVER 6' WATER
ABOVE MAX. LAKE LEVEL.

81

CROSSROADS PARK - 7.24.92 - 12 NOON
BASIN FLOODED ATLEAST ABOUT 8'
ABOVE MAX. LAKE ELEVATION