

Gila River, Arlington, Salt/Verde  
Gillespie Dam, Granite Reef Dam,  
& Hassayampa/Gila Flooding - March 12, 1992

Gila River Erosion - April 1, 1992

Gila River, Gillespie, & Painted Rock Dams - June 1, 1992

Gila River Water in River - August 24, 1992

Gila River Water in River - August 26, 1992

Gila River, Gillespie Dam, SR 85 Flooding - January 11, 1993

Gila River Flooding - January 12, 1993

Gila River Flooding - January 18, 1993

Gila River, Gillespie Area, Painted Rock Dam Flooding March 1, 1993

Gila River Flooding - March 2, 1993

Gila River, Painted Rock Dam Flooding - March 1, 1994

Gila River Flooding - March 12, 1992

Gila River Flooding - April 1, 1992

Gila River Flooding - June 1, 1992

Gila River Flooding - August 24, 1992

Gila River Flooding - August 26, 1992

Gila River Flooding - January 11, 1993

Gila River Aerial View Flooding - January 12, 1993

Gila River Flooding - January 18, 1993

Gila River Flooding - March 1, 1993

Gila River Flooding - March 2, 1993

Gila River Flooding - March 1, 1994

Gila River, Arlington, Salt/Verde  
Gillespie Dam, Granite Reef Dam,  
& Hassayampa/Gila Flooding - March 12, 1992

Gila River Erosion - April 1, 1992

Gila River, Gillespie, & Painted Rock Dams - June 1, 1992

Gila River Water in River - August 24, 1992

Gila River Water in River - August 26, 1992

Gila River, Gillespie Dam, SR 85 Flooding - January 11, 1993

Gila River Flooding - January 12, 1993

Gila River Flooding - January 18, 1993

Gila River, Gillespie Area, Painted Rock Dam Flooding March 1, 1993

Gila River Flooding - March 2, 1993

Gila River, Painted Rock Dam Flooding - March 1, 1994

**Gila River, Arlington, Salt/Verde  
Gillespie Dam, Granite Reef Dam,  
& Hassayampa/Gila Flooding - March 12, 1992**






















3/12/92 PPM JS 126

LSG



5 of 5


32

3/12/92 PPM JS 126

LSG

3/12/92 PPM JS 126

LSG



4 of 5

31

3 of 5

30



**Gila River Erosion - April 1, 1992**



EROSION INSPECTION



EROSION INSPECTION






EROSION INSPECTION



EROSION INSPECTION







EROSION INSPECTION



EROSION INSPECTION



LSG  
EROSION INSPECTION  
4/1/92 15:14 PPM JS 1

52

LSG  
EROSION INSPECTION  
4/1/92 15:14 PPM JS 1

53


LSG  
EROSION INSPECTION  
4/1/92 15:14 PPM JS 1

54

**Gila River, Gillespie, & Painted Rock Dams - June 1, 1992**

C-LINE #52584  
35MM PRINTS





3044 11112  
C-THE #25284

C-LINE #52584  
35MM PRINTS





8855W EME  
27119 MNS



2



2



3



4



4



5



6



6



7



8



9



10



11



12



61




24



1



**Gila River Water in River - August 24, 1992**




LSG  
INSPECTIONS  
8/24/92 1420 PPM JS 1

LSG

8-

71



LSG  
INSPECTIONS  
8/24/92 1420 PPM JS 1


LSG

72



8-24-92 @ Tutwill looking NE  
(SE end of bridge)

1012.03



INSPECTIONS  
8/24/92 1420 PPM JS 1

LSG

74



LSG  
INSPECTIONS  
8/24/92 1420 PPM JS 1

LSG

DST

75



2 of 2 76



8-24-92 @ Tutthill looking E  
(middle of bridge) 1 of 3 77



2 of 3 78



79

3 of 3



8-24-92 @ Tut Hill looking NW  
(SW end of bridge)  
1 of 3 80



81

7 of 3




82

3 of 3

**Gila River Water in River - August 26, 1992**

INSPECTIONS





INSPECTIONS





PIC-MOUNT



PIC-MOUNT



PIC-MOUNT



PIC-MOUNT



PIC-MOUNT



PIC-MOUNT



PIC-MOUNT



PIC-MOUNT



PIC-MOUNT



PIC-MOUNT



PIC-MOUNT




PIC-MOUNT





PIC-MOUNT




**Gila River, Gillespie Dam, SR 85 Flooding - January 11, 1993**



Flooding






Flooding





Flooding






Flooding





July 1997





Flooding

124  
Group 11 of 11 - Photo 2 of 2 - January 11, 1993 - by G. Rodzenko  
View to the northwest of the Old U.S. 80 bridge over the Gila River  
taken from old dip crossing. Note Gillespie Dam in the background.  
Q = 65,000 cfs

LSG  
FLOODING  
1/11/93 JS 126

LSG

123  
Group 11 of 11 - Photo 1 of 2 - January 11, 1993 - by G. Rodzenko  
View to the northwest of the Old U.S. 80 bridge over the Gila River  
taken from old dip crossing. Note Gillespie Dam in the background.  
(The Dam and the deck of the bridge are both perfectly level).

LSG  
FLOODING  
1/11/93 JS 126

LSG

**Gila River Flooding - January 12, 1993**



Flooding



126

LSG

1/12/93 PPM JS 106



128

LSG

1/12/93 PPM JS 106

127

LSG

1/12/93 PPM JS 106

**Gila River Flooding - January 18, 1993**



FLOODING

Gila River, Gillespie Area, Painted Rock Dam Flooding March 1, 1993




Flooding





Foresting





Flooding





Altoona





Flooding





156

gubouff




LSG  
FLOODING  
3/1/93 PPM JS 126



**Gila River Flooding - March 2, 1993**




Flooding



Geology





Flooding





1. Riverbank



2. Industrial site



3. Desert landscape



4. Valley view



Flooding





1964

**Gila River, Painted Rock Dam Flooding - March 1, 1994**



FLOODING







FLOODING








Flooding



Hydrograph



FLOODING





FLOODING








Flooding



grubbs0017





Flooding





Looking  
N



Flooding





12-10-67

