Cove Buttes Dam
Construction Photo Album

A350.904

Cave Buttes Dam
SOUTH END OF OUTLET WORKS
TERRACEING
5-15-78

Property of
Flood Control District of MC Library
Please Return to
2801 W. Durango
Phoenix, AZ 85009

Cave Buttes Dam
Outlet works Main Structure
5-15-78

Cave Butles Dam
Dike #2 BAKFILL OPERATION
Looking Fr. Cave Creek Rd To
West abutment. 1
5-15-78

Cave Butles Dam
Dike #2
Loading 120 TON DUMPS
5-15-78

Cave Buttes Dam,
Dike #2
Steel forms being set
around 45 ϕ conduit
4-11-78



Cave Buttes Dam
Dike 2
45" ϕ PIPE SHOWING
GROUTED JOINTS 4-6-78



Cave Buttes Dams
Dike 2
45"ϕ CONDUIT. SHOWING
REBAR & GROUT. 4-6-78

Cave Buttes Dam
Spill way excavation
South to North
2-3-78

Cave Buttes Dam
Main Structure
Outlet works excavation
2-3-78

Cave Buttes Dam
Spill way excavation
looking South to North
2-3-78

Cave Buttes Dam
excavation area
120 ton Dump Truck
2 Feb 78

Cave Buttes Dam
CUT OFF TRENCH EXCAVATION
MAIN STRUCTURE

2 Feb 78.

Cave Buttes Dam Main
Structure : Cut off Trench
Excavation Looking east to
West.

1-26-78

Cove Buttes Dam.
120 Ton Dump Truck Being
Assembled

1-26-78

Cove Buttes Dam.
120 Ton Dump Truck

1-26-78

Cave Butles Dam.
Flowing Flood Waters. Rd washed out. Looking North along Stream S.W of proposed Dam site
12-29-77.

Cave Butles Dam. Flowing Flood Water on West side of Cave Butles construction. Looking S along stream bed SW of proposed Construction Site
12-29-77

Cave Buttes Dam.
Rd wash out. Looking West
Rd is South West of Construction
site

Cave Butte Dams. 2-28-77
CEMENT Co BORROW AREA WATER
FR UP STREAM OF Cave CREEK DAM
HAS POOLED HERE. PICTURE IS
LOOKING SOUTH OF DAM.

CAVE BUTTES DAM.
UP STREAM SIDE OF CAVE
CREEK DAM
12-29-77.

Cave Buttes Dam
Upstream Side of Cave
Creek Dam
12-2-77.

Cave Buttes Dam.
Stat 107+00 showing culvert
in place. at access rd.
12-28-77.

Cave Buttes Dam.
CULVERT IN PLACE AT
STAT 107+00 AT ACCESS
RD.
12-28-77.

Cave Buttes Dam.
Foundation of Main
structure. Looking
West
14-12-77.

Cave Buttes Dam.
Excavation of Dike #1
Looking West.
14-12-77.

Cave Buttes Dam.
Rock formation during Scaling operation. This section South edge of center section complete stability questionable this date
12-2-77

Cave Buttes Dam. West abutment Main structure. Picture shows completed scaling operation.
12-2-77

Cove Buttes Dam.
Foundation excavation
Main Structure. Looking.
West to East

12-2-77.

Cove Buttes Dam. Main
Structure.
Foundation excavation. Looking
West.

12-2-77.

Cave Bluffs Dam.
Main Structure, Foundation excavation. Looking west to east.

12-2-77.

Cave Buttes Dam.
East abutment. South of
Q main structure

11-29-77.

Cave Buttes Dam.
East abutment. excavation
South of Q main structure

11-29-77.

Cave Buttes Dam
Main structure. Picture
taken from East abutment
looking West
11-23-77.

Cave Buttes Dam
Main structure. Picture
taken from East abutment
looking West 11-23-77.

Cave Buttes Dam.
Main structure
Beginning of Construction
12-2-77.

Cave Buttes Dam
Main Structure
Beginning of Construction
12-2-77.

Cave Buttes Dam
North of Main Structure
looking South of upstream
toe. Dust created due to
lack of watering 12-9-77.

Cave Buttes Dam
Main Structure
Excavation east of abutment
looking West 11-23-77

Cave Buttes Dam.
Dust clouds due to lack of watering of project. Picture taken looking South at up stream toe of main structure 11-9-77.